

Model Name:	JIP4001/JIP4002	Object:	H.W. *S.W.
Subject:	Release SIP Firmware of JIP4001/JIP4002 : sipfxso.106		
Release content			
Bug fixed			
<ol style="list-style-type: none"> 1. Follow the theory of the manufacturer to fix the source code for CPU, otherwise the JIP400X successfully with new hardware. 2. Fix the bug of AutoDNS. The DNS does not follow the DHCP even you enable the “ autodns” function. 			
Featurea dn Function added			
None			
Configuration item changed			
<ol style="list-style-type: none"> 1. Change the default keypad type to RFC2833 2. Change the default payload type to 101 (RFC2833) and 96 (FAX) 3. Remove some configure item from the Web interface, including tone setting, FXO password and commit. Because the Flash ROM is not enough. 4. The configuration will be” commit” if user inputs the new setting and press OK via the Web manage interface. (But user still need to input commit if the new setting are set via CLI) 			
Note			
None			